

Honeywell BW™ Ultra Order Number and Pricing Configurator

▶ Sensor 4 - Toxic 2		▶ Sensor 5 - Toxic 3	
None (dummy sensor)	00	00	None (dummy sensor)
H ₂ S (hydrogen sulfide)	H1	Q1	PID for VOCs (volatile organic compounds)
CO (carbon monoxide)	M1	W4	IR (infrared) for %LEL +% Vol (combustibles)
▶ Sensor 3 - Toxic 1		B1	IR (infrared) for CO ₂ (carbon dioxide)
None (dummy sensor)	00	S1	SO ₂ (sulfur dioxide)
H ₂ S (hydrogen sulfide)	H1	A1	NH ₃ (ammonia)
CO (carbon monoxide)	M1	R1	H ₂ (hydrogen)
▶ Sensor 2 - Combustible Gases		C1	Cl ₂ (chlorine)
None (dummy sensor)	00	D1	NO ₂ (nitrogen dioxide)
%LEL (combustibles), filtered	W1	Z1	HCN (hydrogen cyanide)
%LEL (combustibles), unfiltered	W2	N1	NO (nitrogen monoxide)
%LEL (combustibles), carbon filtered for mining*	W3	M2	CO (carbon monoxide), H ₂ (hydrogen) resistant
▶ Sensor 1 - Oxygen		▶ Housing	
None	00	B	Black housing
O ₂ (oxygen)	X1	Y	Yellow housing
▶ Base Unit		▶ Region	
Base unit	HU	N	North America
		E	Europe
		U	United Kingdom
		C	China/New Zealand
		A	Australia
		B	Brazil
		R	Russia
		X	Other region with 3-pin UK plug
		Y	Other region with 2-pin EU plug
		M	Mining

Order number: HU - [] - [] - [] - [] - [] - [] - []